# INFORMATION ONLY

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE HEALTH AND SAFETY PLAN ACCIDENT PREVENTION SAFETY Manual No. Section No Page:

RFP/ERM-94-00019
Table of Contents, R1

1 of 1 1/12/95

ACCIDENT PREVENTION SAFETY Effective Date 1/12/95
PROGRAM PLAN INT. OPER. UNITS Organization: Environmental Restoration Mgmt

# TABLE OF CONTENTS HEALTH AND SAFETY PLAN ACCIDENT PREVENTION SAFETY PROGRAM PLAN INTEGRATED OPERABLE UNITS

Section No.	<u>Title</u>	Rev No.	Effective <u>Date</u>
	Detailed Table of Contents	0	11/04/94
•95-DMR-ERM-0004	Personnel and Site Condition Changes to OU9 Affects sections 2,5,6,7,8,9,10,APPC	0	1/12/95
1 0	Introduction	0	11/04/94
2 0	Health and Safety Personnel	0	11/04/94
3 0	Facility Characteristics	0	11/04/94
4 0	General Health and Safety Requirements	0	11/04/94
5 0	Hazard Evaluation	0	11/04/94
6 0	Personnel and Air Monitoring	0	11/04/94
7 0	Work Zone-	0	11/04/94
8 0	Personal Protective Equipment	0	11/04/94
9 0	Decontamination Procedures	0	11/04/94
10 0	Emergency Response Plan	0	11/04/94
11 0	Logs, Reports, and Record Keeping	0	11/04/94
12 0	References	0	11/04/94
APPA	Appendix A Personal Protective Equipment and Monitoring Requirements	0	11/04/94
APPB	Appendix B Jacobs' Medical Surveillance Procedures	0	11/04/94
APPC	Appendix C Jacobs Engineering Group Standard Operating Procedures	0	11/04/94

INFORMATION DOCUMENT MODIFICATION REQUEST (DMR) Refer to 1-A01-PAHLY Processing Instructions Date Print or Type All Information (Except Signatures) 12/9/94 DMR No Existing Document Number/Revision 3 New Document Number of Document Number of it RFP/ERM-94-00019 Revision N/A 4 Originator's Name/Phone/Page/Location 5 Document Title Integrated Operable Units Health & Safety Plan C. Coursed 19659 080 Document Type | Procedure

Other HES Plan 7 Document Modification Type (Check only one) □ New □ Revision □ Intent Change ☑ Nonintent Change □ Editorial Correction □ Cancellation 9 Page 10 Step 11 Proposed Modifications 8 Item Change names as shown on revised F2-1 OU9 Project Manager is John Zimmerman, Field Team Leader is Simon Bell, H&S Coordinator is Lisa Nelowet OU14 Project Manager is Bill Fieselman, HSS's are David Spruce, Tom Waddel 2 63 Delete 1st two sentences of Personal Sampling paragraph Modify third sentence to read as follows "Personal sampling will be Sec 6 conducted only when Level C action Levels are reached with direct reading instruments or when otherwise noted in Appendix A. p 4 3 Sec 6 644 Insert new first sentence "Personal sampling will only be performed when directed to by EG&G Radiological Engineering" p 7 4 Sec 6 646 Insert new first sentence "Ambient air sampling for airborne alpha radioactivity will only be performed when directed to by p8 EG&G Radiological Engineering or if action levels for dust are exceeded in an RCA 5591 5 Delete the word "strenuous" from the first sentence of "Heat Stress Monitoring and Work Cycle management " Sec 5 p 42 Delete "even if workers are not wearing impervious clothing." Delete "and body water loss" from 2nd paragraph under "Heat Stress Monitoring Change "oral temperature" to "oral or ear canal temperature " 6 Sec 6 Delete paragraph 6, " The fact that contaminants are listed D 3 12 Justification (Reason for Modification EJO# TP# etc.) Incorporating changes to improve compliance with 29CFR1910 120 and reflect current personnel and site conditions If modification is for a new procedure or a revision list concurring disciplines in Block 13 and enter N/A in Blocks 14 and 15 If modification is for any type of change or a cancellation organizations are listed in Block 13 then Concurror prints and signs in Block 14 and dates in Block 15 13 Organization 14 Print and Sign (if applicable) 15 Date (if applicable) EOM K D Anderson RE D Hyder ÍΗ M D Schreckengast IA OU B D Peterman 64 16 Originator's Supervisor Craig Cowdery/6953/5466/080 Accelerated Review Yes 🗇 **10** 🗖 Responsible Manager (print Craig Cowdery REVIEWED FOR CLASSIFICATION/UCNI BY DATE

Refer to 1-A01-PPG-001 for Processing Instructions
Print or Type All Information (Except Signatures)

DMR No 94 DMR

Item	10 0				
	9 Page	10 Step	11 Proposed Modifications		
7	Sec 9 p 2	911	Change "dispose of glove" to "dispose of outer gloves"  Add built after "Remove respirator builte" to read "Remove and dispose of inner gloves "		
8	Sec 8 p 2	8 1 1	Change first paragraph to read "For activities to be conducted under this plan, personnel will wear Level D as defined in Section 8 1 3 "		
9	Sec 8	813	Delete paragraphs 2 and 3  Add builte after dosimeter badge bullet to read "nitrile gloves if hand contact with potentially contaminated materials is		
10	p 5 Sec 5 p 14	5 2 2	Integrate new chemicals as shown into Section 5 2 2 alphabetically		
11	Sec 5 p 2	5 2 Table 5-1	Integrate new chemicals as shown into Table 5-1 chemical Exposure Hazard Summary alphabetically		
12	Sec 5 p 38	5 5 3	Change "Utility clearance will be completed before work begins " to "Utility clearance will be completed by the client before work begins "		
13	Sec 5 p 38	5 5 3	Change (SOP 7 7) to read SOP 7 7a		
.4	Sec 5 p 38	5 5 3	Delete "which uses hand-augering to confirm the absence of buried utilities,"  Change the last sentence to read "A copy of Jacobs' SOP 7 7a is provided in Appendix C		
15	Appendix C	SOP 7 7	Delete SOP 7 7, add new SOP 7 7a Utility Clearance at Rocky Flats Plan (7 pages)		
16	Sec 7 p 4	715	The fourth bullet will read as follows "All visitors will receive a site specific safety briefing, and will be escorted at all times. Visitors in areas requiring Level A, B or C PPE must have the equivalent training and PPE as the onsite worker to gain entry."		
17	Sec 7 p 4	7 1 5	Add builet after above statement that reads, "Visitors in areas requiring Level D PPE must have Level D PPE, receive a specific safety briefing, and will be escorted at all times		
18	Sec 7 p 4	715	Add paragraph/sentenceafter 'All site visitor access must be clearly documented "bullet to read "If visitor does not superirent documentation but insists that he/she enters area the following actions are to be taken "		
19	Sec 7 p 4	7 1 5	Add builtet after above new statement to read "On site HSS or HSST will shut down activities, secure area by monitoring with instrumentation, and contact HSO/HSS or Site Manager		
20	Sec 7 pg 5	7 2	Is first sentence delete "heavy equipment or"		
21	Sec 6 p 4	6 3	Add new text to end of Action Levels paragraph When action levels are reached which, according to Appendix A, require "evacuation and reevaluation," site workers must move to an area where direct reading instrumentation shows airborne concentrations are below the action levels of concern The HSS/HSST must contact the Health & Safety Coordinator to determine further action		

Reter to 1-A01-PPG-001 for Processing Instructions
Print or Type All Information (Except Signatures)

25 95-DMR-ERM-DOY DMR No. 94-DMR- In 1/9/95

8 Item	9 Page	10 Step	11 Proposed Modifications	
	1	-	The state of the s	
22	Sec 6	6 3	Add to end of 1st paragraph "All monitoring will be in the breathing zone unless otherwise specified in Appendix A."	
23	Sec 10 p 2	10 2 1	Add EG&G Operations Manager Representative Change 'Kent Mahana" to "Lisa Nelowet "	
24	Sec 10 p 3	10 2 1	Add EG&G Operations Manager Representative	
25	Sec 10 p 8	10 3 1	Add Operations Manager Representative, as listed in Tables 10-1, 10-2, must be notified of any unplanned releases	
26	Sec 10 p 9	10 3 2	Change "Kent Mahana" to "Lisa Nelowet"	
27	Sec 5 p 5-31	T5-4	Modify as shown	
28	Sec 6	6 3	Replace "every 15 minutes" to "whenever site conditions change" in first paragraph	
9		F7-1	Delete figure	
30	Sec 7 p 5	721	Delete 1st sentence	

Manual: Section: Page: Organization: RFP/ERM-94-00019 TOC (Rev. 0) vii of x11 Environmental Management

## TABLE OF CONTENTS

### (Continued)

	Page
	10.4.4 First-Aid Register
	10.4.5 Vehicle Accident Reporting Procedure 10-11
10.5	ROCKY FLATS PLANT REPORTING PROCEDURE 10-11
11.0 LOGS	, REPORTS, AND RECORD KEEPING
11.1	HEALTH AND SAFETY LOGBOOK
11.2	CALIBRATION LOGS
12.0 REFE	RENCES
List of Figu	res
Figure 2-1	Integrated OU Project Organization Chart Rocky Flats Plant 2-2
Figure 3-1	Rocky Flats Plant - Location Map
Figure 3-2	Rocky Flats Plant - General Map
Figure 3-3	Rocky Flats Plant Building Location Map
Figure 7-1	Typical Site Control Layout
List of Tab	les
Table 3-1	Summary of Nonintrusive Activities by Integrated Operable Units
	and Individual Hazardous Substance Sites
Table 5-1	Chemical Exposure Hazard Summary
Table 5-2	Integrated Operable Unit Location and Hazard Summary by
	Individual Hazardous Substance Site
Table 5-3	Radionuclides
Table 5-4	Asphalt and Concrete Removal and Sampling 5-31
Table 5-5	Polychlorinated Biphenyl Sampling

Manual: Section: Page: Organization: RFP/ERM-94-00019 TOC (Rev. 0) viii of xii

Environmental Management

# TABLE OF CONTENTS

### (Continued)

		Page
Table 5-6	Polychlorinated Biphenyl Sampling	. 5-33
Table 5-7	Soil-Gas Survey	. 5-35
Table 5-8	Surface Water and Sediment Sampling	. 5-36
Table 6-1	Survey Instrumentation	6-6
Table 9-1	Radioactive Contamination Limits	9-3
Table 10-1	Emergency Telephone Numbers - Fieldwork	. 10-2
Table 10-2	Pager Numbers	. 10-3

#### List of Appendices

APPENDIX A Personal Protective Equipment and Monitoring Requirements

APPENDIX B Jacobs' Medical Surveillance Procedures

APPENDIX C Jacobs Engineering Group Standard Operating Procedures

#### LIST OF EFFECTIVE PAGES

)4
)4
)4
)4
14
14
14
14

EG&G ROCKY FLATS PLANT Integrated Operable Units	Manual Section	RFP/ERM-94-00019 9 (Rev 0) 2 of 3
Health and Safety Plan	Page	
	Organization	Environmental Management

- Wash and rinse gloves and boots with nonphosphate detergent and water
- Remove and dispose of outer gloves and coveralls
- Remove respirator (for Level C) and clean
- Remove and dispose of inner gloves
- Wash hands and face with soap and water

#### 9.1.2 Radioactive Contamination

75-DIN R-8-RIN-0004

Personnel with identified radioactive contamination that cannot be readily removed in the field will be transported to the designated RFP Occupational Health facility (Building 122) for decontamination. Decontamination will be performed in accordance with EG&G EMRG 2 3, Wounds and Skin Contamination, in consultation with the EG&G Environmental Management Radiological Engineer.

#### 9.2 HEAVY EQUIPMENT -

Heavy equipment decontamination will be performed at the designated RFP decontamination pad Level C is required for decontaminating heavy equipment such as field vehicles, augers, and drill rigs. Personnel Level C decontamination will be accomplished as described in RFP EMD Operating Procedures Manual Volume I, Field Operations, FO 12, Decontamination Facility Operations, Revision No. 2, and FO 04, Heavy Equipment Decontamination

#### 9.3 SMALL EQUIPMENT

Small equipment will be protected from contamination by draping, masking, or otherwise covering as much of the instruments as possible with plastic, without hindering the operation of the unit